

KATHY HOCHUL Governor

MARIE THERESE DOMINGUEZ Commissioner

OPERATOR ID 01684

YANKEE TRAILS INC. 569 3RD AVE RENSSELAER, NY 12144

Dear Motor Carrier:

Enclosed is the annual New York State Department of Transportation Bus Inspection System Operator Profile that summarizes the results of vehicle inspections performed on your fleet by the Department during the last State Fiscal Year (April 1, 2022, to March 31, 2023). For regular inspections, the profile identifies the number and percentage of vehicles that passed or were placed Out-of-Service (OOS) due to one or more OOS defects. It is the Department's continued goal to have all operators pass at least 90% of their scheduled safety inspections. The current statewide average OOS rate is 4.1% (95.9% pass rate).

We congratulate those operators who have achieved the goal of a 90% or greater pass rate. Your commendable performance indicates a strong dedication to safety and a commitment to sound maintenance standards and practices.

Operators who have a passing rate of less than 90%, it is requested that your organization examine the enclosed profile inspection data and immediately update your maintenance program in order to achieve the Department's stated goal. Your Regional Bus Inspection Program Supervisor is available to review the actions being taken and provide assistance, if necessary, to address any needed changes.

For those operators whose OOS rate is 25% or greater and fall under the Department's enforcement program, you will be contacted shortly to address your unacceptable poor performance. Actions include, but are not limited to, civil penalties, unannounced vehicle inspections, denial of B & C privileges, and compliance reviews.

You can find contact information for the Supervising Motor Vehicle Inspector in your area at: https://www.dot.ny.gov/divisions/operating/osss/bus/contact-list

Please visit https://www.dot.ny.gov/divisions/operating/osss/bus for program updates.

New York State Department of Transportation Office of Modal Safety and Security Passenger Carrier Safety Bureau